

iQM2 Corrective Action Report

November 2025

Analyzer

Model: GEM® Premier 5000
 Area: OKBH
 Name: GP5000
 S/N: 21047807

| Cartridge | Date/Time | Event | Corrective Action | Result |
|--|------------------------|--|--|-----------|
| Lot No.: 250717O S/N: 0000000005012 38929 Exp. Date: 10.12.2025 | 28.11.2025 15:03:45 | Micro Clot Detected | Sensors Rinsed and Checked | Cleared |
| | 28.11.2025 15:02:30 | Solution A Error for Cl ⁻ | Sensor Output Adjusted | Corrected |
| | 28.11.2025 02:12:04 | Solution C Error for pO ₂ | Sensor Output Adjusted | Corrected |
| | 25.11.2025 20:18:13 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 15.11.2025 17:28:40 | CO-Ox Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 10.11.2025 12:40:27 | Interference Detected for sample for pH. Operator: | Operator Notified. Sensor Output Adjusted | Cleared |
| | 10.11.2025 11:33:46 | Interference Detected for sample for pH. Operator: | Operator Notified. Sensor Output Adjusted | Cleared |
| | | | | |
| Lot No.: 250625B S/N: 0000000005012 19907 Exp. Date: 09.11.2025 | 09.11.2025 16:28:04 | Cartridge Removed. Samples Remaining = 44. No. of Solution B Adjustments = 61 | | |
| | 06.11.2025 21:50:54 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 06.11.2025 21:50:54 | CO-Ox Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 06.11.2025 21:50:54 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 05.11.2025 16:48:47 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 04.11.2025 05:12:23 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 04.11.2025 05:12:22 | CO-Ox Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 04.11.2025 05:12:22 | tBili Absorbance Error Detected. Operator: | Result Flagged | Cleared |
| | 03.11.2025 02:12:05 | Solution C Error for pO ₂ | Sensor Output Adjusted | Corrected |
| | | | | |