iQM2 Corrective Action Report

August 2025

Analyzer

Model: GEM® *Premier 5000*
Area: KAIM
Name: GP5000
S/N: 21047812

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250609U S/N: 0000000005012 04669 Exp. Date: 09/25/2025	08/31/2025 14:54:18	Solution A Error for Lac	Sensor Output Adjusted	Corrected
	08/28/2025 14:53:58	Solution A Error for Lac	Sensor Output Adjusted	Corrected
	08/28/2025 00:09:05	Solution A Error for Lac	Sensor Output Adjusted	Corrected
	08/27/2025 12:08:46	Solution E Error for pO_2	Sensor Output Adjusted	Corrected
	08/27/2025 02:14:05	Solution C Error for pO_2	Sensor Output Adjusted	Corrected
Lot No.: 250509U S/N: 0000000005011 76341 Exp. Date: 09/04/2025	08/25/2025 16:16:51	Cartridge Removed. Samples Remaining = 0. No. of Solution B Adjustments = 27		
	08/22/2025 11:44:41	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/20/2025 18:58:52	Solution A Error for pO_2	Sensor Output Adjusted	Corrected
	08/20/2025 00:28:04	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/19/2025 16:39:00	Intraspect Detected during sample measurement for Ca^{++}. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/19/2025 11:08:09	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/18/2025 14:10:17	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/17/2025 11:07:14	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/17/2025 09:41:53	Solution A Error for Glu, Lac	Sensor Output Adjusted	Corrected
	08/17/2025 00:22:01	Solution A Error for Lac, Glu	Sensor Output Adjusted	Corrected
	08/15/2025 18:58:11	Micro Clot Detected	Sensors Rinsed and Checked	Cleared
	08/15/2025 18:56:56	Solution A Error for Cl^-	Sensor Output Adjusted	Corrected
	08/15/2025 16:43:36	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/14/2025 16:30:01	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/13/2025 16:43:22	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/12/2025 10:55:26	Micro Clot Detected	Sensors Rinsed and Checked	Cleared
	08/12/2025 10:54:10	Solution A Error for Cl^-	Sensor Output Adjusted	Corrected
	08/11/2025 21:51:59	Intraspect Detected during sample measurement for Cl^-. Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	08/08/2025 23:01:55	Solution A Error for Lac	Sensor Output Adjusted	Corrected
	08/08/2025 10:53:57	Solution A Error for pO_2	Sensor Output Adjusted	Corrected
	08/06/2025 11:43:32	High Turbidity Detected during sample measurement for CO-Ox. Operator:	Result Flagged	Cleared
	08/05/2025 02:12:04	Solution C Error for pO_2	Sensor Output Adjusted	Corrected
	08/04/2025 22:17:54	Solution A Error for Lac	Sensor Output Adjusted	Corrected

iQM2 Corrective Action Report (continued...)

Cartridge	Date/Time	Event	Corrective Action	Result