

iQM2 Corrective Action Report

April 2025

Analyzer

Model: GEM® Premier 5000
 Area: ARIM
 Name: GP5000
 S/N: 23023618

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250228T S/N: 0000000005011 07097 Exp. Date: 22.05.2025	22.04.2025 10:54:21	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
Lot No.: 250127V S/N: 0000000005010 75707 Exp. Date: 01.05.2025	21.04.2025 17:07:20	Cartridge Removed. Samples Remaining = 0. No. of Solution B Adjustments = 94		
	21.04.2025 17:06:31	Cartridge Removed. Samples Remaining = 0. No. of Solution B Adjustments = 94		
	21.04.2025 17:05:18	High Turbidity Detected during sample measurement for CO-Ox. Operator: 72855	Result Flagged	Cleared
	14.04.2025 11:35:58	Micro Clot Detected in sample for K ⁺ , Cl ⁻ , pH, Ca ⁺⁺ . Operator: NMB20200074561	Operator Notified. Sensors Rinsed and Checked	Cleared
	14.04.2025 11:23:52	CO-Ox Absorbance Error Detected. Operator: NMB20200074561	Result Flagged	Cleared
	08.04.2025 18:04:45	Interference Detected for sample for Na ⁺ , K ⁺ , Ca ⁺⁺ . Operator: 76755	Operator Notified. Sensor Output Adjusted	Cleared
	06.04.2025 13:56:30	Interference Detected for sample for Ca ⁺⁺ . Operator: 76755	Operator Notified. Sensor Output Adjusted	Cleared
	02.04.2025 10:52:44	Solution A Error for Na ⁺ , Ca ⁺⁺	Sensor Output Adjusted	Corrected