

## iQM2 Corrective Action Report

December 2025

## Analyzer

Model: GEM® Premier 5000  
 Area: POCT15TALI  
 Name: GEM-5000  
 S/N: 20075305

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250814O S/N: 0000000005012 64826 Exp. Date: 18.01.2026	18.12.2025 20:02:46	Solution A Error for $pO_2$	Sensor Output Adjusted	Corrected
Lot No.: 250716H S/N: 0000000005012 37515 Exp. Date: 18.01.2026	18.12.2025 16:37:50	Cartridge Removed. Samples Remaining = 150. No. of Solution B Adjustments = 48		
	18.12.2025 16:36:14	Cartridge Removed. Samples Remaining = 150. No. of Solution B Adjustments = 48		
	18.12.2025 16:30:55	Cartridge Removed. Samples Remaining = 150. No. of Solution B Adjustments = 48		
	18.12.2025 15:50:26	Solution A Error for Lac	Sensor Output Adjusted	Corrected
Lot No.: 250716H S/N: 0000000005012 37510 Exp. Date: 19.12.2025	18.12.2025 14:31:54	Cartridge Removed. Samples Remaining = 39. No. of Solution B Adjustments = 64		
	18.12.2025 14:30:39	Persistent Solution D Error for $pO_2$	Sensor Output Adjusted	$pO_2$ Disabled
	17.12.2025 16:52:10	Intraspect Detected during sample measurement for Cl <sup>-</sup> . Operator: 9438	Operator Notified. Sensor Value Discarded.	Discarded
	16.12.2025 00:20:19	Solution D Error for $pO_2$	Sensor Output Adjusted	Corrected
	15.12.2025 14:30:33	Solution D Error for $pO_2$	Sensor Output Adjusted	Corrected
	12.12.2025 06:52:41	Solution A Error for $pO_2$	Sensor Output Adjusted	Corrected