

iQM2 Corrective Action Report

August 2025

Analyzer

Model: GEM® Premier 5000
 Area: NEUJ
 Name: NEUJ1
 S/N: 23065057

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250625B S/N: 0000000005012 19894 Exp. Date: 09/27/2025	08/29/2025 14:54:02	Solution A Error for Lac	Sensor Output Adjusted	Corrected
Lot No.: 250416F S/N: 0000000005011 54898 Exp. Date: 08/27/2025	08/27/2025 06:24:37	Cartridge Removed. Samples Remaining = 32. No. of Solution B Adjustments = 4		
	08/25/2025 06:54:19	Micro Clot Detected	Sensors Rinsed and Checked	Cleared
	08/25/2025 06:52:52	Solution A Error for Cl ⁻	Sensor Output Adjusted	Corrected
	08/12/2025 02:12:11	Solution C Error for pO ₂	Sensor Output Adjusted	Corrected
	08/10/2025 02:12:06	Solution C Error for pO ₂	Sensor Output Adjusted	Corrected