

iQM2 Corrective Action Report

May 2025

Analyzer

Model: GEM® Premier 5000
 Area: ARIM
 Name: GP5000
 S/N: 23023618

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250228T S/N: 0000000005011 07086 Exp. Date: 21.06.2025	22.05.2025 08:15:22	Cartridge Removed. Samples Remaining = 147. No. of Solution B Adjustments = 3		
	22.05.2025 08:14:03	Cartridge Removed. Samples Remaining = 147. No. of Solution B Adjustments = 3		
	22.05.2025 02:31:08	Cartridge Removed. Samples Remaining = 147. No. of Solution B Adjustments = 3		
	22.05.2025 02:30:33	Persistent Solution D Error for pO_2	Sensor Output Adjusted	pO_2 Disabled
Lot No.: 250228T S/N: 0000000005011 07097 Exp. Date: 22.05.2025	20.05.2025 23:27:36	Cartridge Removed. Samples Remaining = 0. No. of Solution B Adjustments = 18		
	20.05.2025 23:12:04	Cartridge Removed. Samples Remaining = 0. No. of Solution B Adjustments = 18		
	16.05.2025 20:52:36	Intraspect Detected during sample measurement for Cl ⁻ . Operator: 75851	Operator Notified. Sensor Value Discarded.	Discarded
	15.05.2025 22:48:02	Intraspect Detected during sample measurement for Cl ⁻ . Operator: 73366	Operator Notified. Sensor Value Discarded.	Discarded