

## iQM2 Corrective Action Report

November 2025

**Analyzer**

Model: GEM® Premier 5000  
 Area: OKB  
 Name: GP5000  
 S/N: 19042798

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250717O S/N: 0000000005012 38901 Exp. Date: 09.12.2025	29.11.2025 05:39:43	Intraspect Detected during sample measurement for Ca <sup>++</sup> . Operator:	Operator Notified. Sensor Value Discarded.	Discarded
	26.11.2025 06:27:12	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	13.11.2025 04:51:18	Solution A Error for pO <sub>2</sub>	Sensor Output Adjusted	Corrected
Lot No.: 250609J S/N: 0000000005012 03928 Exp. Date: 08.11.2025	08.11.2025 19:27:44	Cartridge Removed. Samples Remaining = 116. No. of Solution B Adjustments = 24		
	05.11.2025 12:53:57	Solution A Error for pO <sub>2</sub>	Sensor Output Adjusted	Corrected
	04.11.2025 07:04:50	Interference Detected for sample for Ca <sup>++</sup> . Operator:	Operator Notified. Sensor Output Adjusted	Cleared