

iQM2 Corrective Action Report

December 2025

Analyzer

Model: GEM® Premier 5000
 Area: POCT06KCLI
 Name: GEM5
 S/N: 19042829

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250729G S/N: 0000000005012 48561 Exp. Date: 12.01.2026	12.12.2025 17:16:11 12.12.2025 17:15:36	Cartridge Removed. Samples Remaining = 148. No. of Solution B Adjustments = 1 Persistent Solution D Error for pO_2	Sensor Output Adjusted	pO_2 Disabled
Lot No.: 250716H S/N: 0000000005012 37496 Exp. Date: 03.01.2026	12.12.2025 07:56:52 12.12.2025 07:39:27 12.12.2025 02:52:53 11.12.2025 17:14:47 03.12.2025 12:15:48	Cartridge Removed. Samples Remaining = 89. No. of Solution B Adjustments = 21 Persistent Solution A Error for pCO_2 Micro Clot Detected Interference Detected for sample for Na^+ , K^+ , pCO_2 . Operator: 7412 Solution A Error for pO_2	Sensor Output Adjusted Sensors Rinsed and Checked Operator Notified. Sensor Output Adjusted Sensor Output Adjusted	pCO_2 Disabled pCO_2 Temporarily Disabled Cleared Corrected
Lot No.: 250716H S/N: 0000000005012 37492 Exp. Date: 08.12.2025	03.12.2025 11:27:22	Cartridge Removed. Samples Remaining = 1. No. of Solution B Adjustments = 1		