

iQM2 Corrective Action Report

September 2019

Analyzer

Model: GEM® Premier 5000
 Area: VET CLINIC
 Name: GP5000
 S/N: 18102177

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 190516A S/N: 0000000005000 10993 Exp. Date: 21.10.2019	26.09.2019 15:07:29	Cartridge Removed. Samples Remaining = 138. No. of Solution B Adjustments = 2		
	26.09.2019 14:30:34	Cartridge Removed. Samples Remaining = 138. No. of Solution B Adjustments = 2		
	26.09.2019 14:29:59	Persistent Solution D Error for pO_2	Sensor Output Adjusted	pO_2 Disabled
	26.09.2019 07:35:23	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	24.09.2019 00:20:04	Solution D Error for pO_2	Sensor Output Adjusted	Corrected
	20.09.2019 21:09:59	Persistent Solution D Error for Lac	Sensor Output Adjusted	Lac Disabled
Lot No.: 190516A S/N: 0000000005000 10975 Exp. Date: 20.09.2019	20.09.2019 17:44:41	Cartridge Removed. Samples Remaining = 71. No. of Solution B Adjustments = 27		
	18.09.2019 07:35:01	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	18.09.2019 07:34:43	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	16.09.2019 22:57:53	Solution A Error for pO_2	Sensor Output Adjusted	Corrected
	13.09.2019 20:01:16	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	13.09.2019 20:00:59	CO-Ox Absorbance Error Detected. Operator:	Result Flagged	Cleared
	09.09.2019 02:11:14	Solution C Error for pO_2	Sensor Output Adjusted	Corrected