

iQM2 Corrective Action Report

September 2025

Analyzer

Model: GEM® Premier 5000
 Area: NEUJ
 Name: NEUJ1
 S/N: 23065057

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250515U S/N: 0000000005011 81500 Exp. Date: 10/28/2025	09/27/2025 14:47:30 09/27/2025 14:46:55	Cartridge Removed. Samples Remaining = 150. No. of Solution B Adjustments = 3 Persistent Solution E Error for pO_2	Sensor Output Adjusted	pO_2 Disabled
Lot No.: 250625B S/N: 0000000005012 19894 Exp. Date: 09/27/2025	09/27/2025 08:08:17 09/18/2025 00:20:18 09/17/2025 02:12:07 09/12/2025 22:56:43 09/02/2025 12:20:08	Cartridge Removed. Samples Remaining = 111. No. of Solution B Adjustments = 23 Solution D Error for pO_2 Solution C Error for pO_2 Solution A Error for Lac Solution D Error for pO_2	Sensor Output Adjusted Sensor Output Adjusted Sensor Output Adjusted Sensor Output Adjusted	Corrected Corrected Corrected Corrected