

iQM2 Corrective Action Report

September 2025

Analyzer

Model: GEM® Premier 5000
Area: IFLS
Name: IFLS
S/N: 24077514

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250502R S/N: 0000000005011 69681 Exp. Date: 10/03/2025	09/23/2025 18:57:49	Solution A Error for Ca ⁺⁺	Sensor Output Adjusted	Corrected
	09/16/2025 02:50:04	Solution A Error for Lac	Sensor Output Adjusted	Corrected
	09/14/2025 18:30:12	CO-Ox Micro Clot Detected	CO-Ox Rinsed and Checked	Cleared
	09/02/2025 17:43:27	Solution A Error for Lac	Sensor Output Adjusted	Corrected
Lot No.: 250502R S/N: 0000000005011 69682 Exp. Date: 09/01/2025	09/01/2025 13:35:38	Cartridge Removed. Samples Remaining = 111. No. of Solution B Adjustments = 43		