

# iQM2 Corrective Action Report

December 2025

**Analyzer**

Model: GEM® Premier 5000  
Area: OKBH  
Name: GP5000  
S/N: 21047807

Cartridge	Date/Time	Event	Corrective Action	Result
Lot No.: 250902S S/N: 0000000005012 80020 Exp. Date: 10.01.2026	10.12.2025 23:06:15	Solution A Error for $pO_2$	Sensor Output Adjusted	Corrected
Lot No.: 250717O S/N: 0000000005012 38929 Exp. Date: 10.12.2025	10.12.2025 17:15:08	Cartridge Removed. Samples Remaining = 45. No. of Solution B Adjustments = 55		
	09.12.2025 00:22:24	Solution D Error for $O_2Hb$ , $COHb$ , $MetHb$ , $HHb$ , $tHb$ , $tBili$	Sensor Output Adjusted	Corrected
	06.12.2025 06:51:20	Solution A Error for $Cl^-$	Sensor Output Adjusted	Corrected